

Open cases	Description and comments
Real-Time Clock (RTC) inaccuracy.	The time of day will be ahead of the actual time by 3-5 seconds per day. Requirement is no more than 2 seconds per day. #14616
Daylight Savings Changes do not work.	The automatic changing of time for Daylight Savings Time start and end do not work. #14517
Using LAN B could cause different problems	Example: -If a Hub is used in the Ethernet connection to port B, communication errors can occur. Recommend to use Switch instead. #14773 & #15065
USB Flash Drive incompatibility issue	Always recommended to use Industrial Grade of the USB Flash sticks to avoid disturbance and incompatibility issues. #15108